


Tools-Activation



Parameter-Tools Activation

Description

*Meaningful
tool names*

Each tool is identified with a name which is used during tool change prompts.

Color

*Colors in the
graphical
display*

The Color parameter for each tool is used in the graphical display of the data. As a result, it is easy to adapt the color display to suit your own requirements or to harmonize with the CAD program you are using.

Clicking the colored box opens a dialog box in which you can select a new color. All colors supported by the current Windows display settings can be selected.

Activation

Activating tools individually

Each tool can be individually enabled or blocked. Inactive tools are simply ignored in the graphical display and the commands for them are skipped. Switching tools ON/OFF is even easier by clicking with the mouse on to the colored toolbox directly above the displayed graphics.

Spindle speed

It is possible to assign a spindle speed to each tool. This is set using a defined analog or PWM output when the tool is used.